

BANANA-RITE LTD.

Meadowside, Prees Green, Whitchurch, Shropshire, SY13 2BL
Tel. +44(0) 1948 840784. VAT No. 320 0661 15. Reg in UK No. 1548824 Fax. +44(0) 1948 840881
e-mail: info@banana-rite.co.uk URL: www.banana-rite.co.uk

HEALTH, SAFETY AND DATA SHEET FOR USE WITH CATALYTIC GENERATORS & "ETHY-GEN II" FOR THE PRODUCTION OF ETHYLENE

THE GENERATOR

Always use with care.

Always keep the power supply cable in good condition.

Always maintain an efficient earth path.

Always be sure to place the Generator in a secure position and on a firm base when in use.

If the power supply is inside the room it must be through a moisture proof plug and socket. The Generator uses 160 watts, a 3-amp fuse is recommended. No other sophisticated electrical precautions are necessary, if used strictly in accordance with the instructions it is impossible to create an explosive situation.

"ETHY-GEN II" CONCENTRATE FOR USE IN THE GENERATOR HAZARDOUS PROPERTIES

CAUTION — HIGHLY FLAMMABLE LIQUID (Flash point 12.8°C) AVOID NAKED FLAME (In case of fire, smother the flames with sand, or use a foam fire extinguisher, call the fire brigade.)

IT IS NOT CORROSIVE, IT IS A MILD IRRITANT (In case of accidental contact with skin, wash with warm soapy water.)

AVOID CONTACT WITH EYES (In case of accidental contact, irrigate the eyes with clean fresh water for at least fifteen minutes, seek medical attention.)

CAUTION — CONTAINS ETHANOL "ETHY-GEN II" Concentrate can be harmful or fatal if taken internally. If taken internally, induce vomiting. Seek immediate medical attention. Always use with great care.

STORAGE OF "ETHY-GEN II" CONCENTRATE

"Ethy-Gen II" Concentrate should always be stored in conditions appropriate to a highly flammable liquid, quantities of up to 50 litres total may be kept in a suitable bin or cupboard in a warehouse, the bin or cupboard must be labelled "Highly Flammable". Quantities greater than 50 litres require special storage facilities. Please refer to "Highly flammable liquids and liquefied petroleum gases regulations, 1972". Further information is given in the Health & Safety Executive Guidance Note CS/2. Both notices are available from HM Stationary Offices.